



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	David Shaver Manager				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0070019		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, December 17, 2008		
Start Date/Time:	12/17/2008 8:00:00 AM		
End Date/Time:	12/17/2008 11:00:00 AM		
Last Inspection:	Tuesday, November 18, 2008		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 9 Deg. F. InspectionID Report Number: 1869

Types of Operations

Accepted by: jhelfric

1/7/2009

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: CENTENNIAL MINE

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages
---------	----------

6,602.02	Total Permitted		
35.27	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

✓ Underground **✓** Federal ☐ Surface ✓ State ☐ Loadout County

√ Fee Processing ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Citation #10030 pending abatement. Permitting actions relative to this citation have been conditionally approved by the Division pending receipt of clean copies. Once the Division gives final approval the citation will be terminated.

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date Wednesday, December 17, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070019

Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Wednesday, December 17, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.

 | Complete |
 - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
<u>1.</u>	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	V		V	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	П	П	П	

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Wednesday, December 17, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area.

4.a Hydrologic Balance: Diversions

The diversion alng the side of the main access road in the upper reach has had large rocks roll into the diversion. The rocks are completely blocking the diversion and will require a large piece of equipment to remove. Dave Shaver made a note of the blockage and is making arrangements to have the rocks removed.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2008 water monitoring is in the EDI website but has not been uploaded. Water monitoring is current.

8. Noncoal Waste

The noncoal waste items identified on the previous inspection had been collected and disposed of properly.